

GAMBELL AIRPORT

Contents:

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing predicted pavement conditions
- Age map showing pavement age as of January 2003
- A Branch PCI Condition Report
- A Section PCI Condition Report

Airport Information:

- Location:
Gambell is located on the northwest tip of Saint Lawrence Island in the Bering Sea, approximately 190 miles east south east of Nome. The airport is located on a narrow sand-gravel spit just south of the village. The Bering Sea borders the west side of the runway and Troutman Lake borders it on the east.
- District: Western District, Northern Region
- Airport Manager: Jerry Oliver
- District Maintenance Manager: Jim Adams
- Pavement Surface: Asphalt Concrete
- Last Pavement Construction: 1999
- Pavement layout: Runway 16-34, Taxiway A and Apron.
- Design Aircraft: DC-6
- 2001 Enplanements: 3,337
- Airport Class: Non-Primary
- Last pavement condition survey: 2002
- Next planned pavement condition survey: 2005
- 2002 reported pavement maintenance and/or changed conditions: None Reported.
- Recommendations: See PCI maps